



USED MACHINE INSPECTION REPORT PAVER

1. General Information

Machine Model	SUMITOMO HAGOC-8	Serial No.	SMTA60CBPJ0000614
Year	2019	Operating Hours	1015
Screed	JP 2360	Screed No.	//
Paving Width	2,3 - 6 m	Screed Extensions	//
Levelling System / Make / Type	Mobel Motec CANZ	Levelling System Configuration	2x Sonic Ski 1x Slope sensor
Customer		Date, Location	15-06-23 / Spain

2. Equipped with following Options

Sun roof	<input checked="" type="checkbox"/>	Side curtains	<input type="checkbox"/>	Cabin	<input type="checkbox"/>
Working lights	<input checked="" type="checkbox"/>	Additional working lights	<input type="checkbox"/>	Warning beacon	<input type="checkbox"/>
Screed lock	<input checked="" type="checkbox"/>	Screed anti-climbing lock	<input checked="" type="checkbox"/>	Spacer blocks, screed	<input type="checkbox"/>
Screed Diesel heating	<input type="checkbox"/>	Screed gas heating	<input type="checkbox"/>	Electric heating, screed	<input checked="" type="checkbox"/>
ThermoControl	<input checked="" type="checkbox"/>	Tropicalised	<input type="checkbox"/>	Sound insulation	<input type="checkbox"/>
Central lube, paver	<input checked="" type="checkbox"/>	Central lube, screed	<input checked="" type="checkbox"/>	Automatic steering	<input type="checkbox"/>
Diesel transfer pump	<input type="checkbox"/>	Emulsion tank	<input type="checkbox"/>	Screed tensioning device	<input type="checkbox"/>
2 Limit switches or USS for the auger	<input checked="" type="checkbox"/>	Screed load device	<input type="checkbox"/>	Other options	<input type="checkbox"/>

3. CE Conformity of the Machine:

	yes	no	s. below
The has already been in free circulation within the European Union (i.e. a CE label is affixed on the machine).	X		a)
No alterations have been made on the machine (e.g. increase of output, alteration of the functions and safety devices etc.).	X		
If the previous question was answered with "no", a risk analysis must be made:			
Have any new or additional safety risks arisen ? (If so, specify the reason under item 4)		X	b)

a) If the answer is no, the used machine must not be sold within the European Union.

b) If the answer is yes the used machine must not be sold within the European Union.

In both cases there is no CE conformity for the machine.

Machine is CE conform: yes, non (not for resale in the European Union)

Operating instructions with machine: no yes, Qty: , Language:

Spare parts lists with machine: no yes, Qty: , Language:

Place, Date, Name/Signature

Spain 15-06-23 Paolo Belle

Please Note: If this Used Machinery Inspection Report is not properly completed, the machine cannot be correctly assessed and unnecessary costs will arise.

MACHINE PARTS SERVICE



4. Assemblies and Components

Assess the condition of the assemblies and components using a scale of 1 – 5 :
5 = as new, 4 = good, 3 = average, 2 = below average, 1 = poor

	Condition (1 - 5)	Remarks (mm / %)
Appearance		
1 Paint work	5	
2 Superstructure	5	
3 Frame and welding work	5	
4 Control panel / instruments (EPM/ASS)	5	
5 Seat with console	5	
6 Hopper wings, hinges & hinge rods	5	
Conveyor System		
7 Hopper floor plates (mm)		10 mm
8 Conveyor chain covers (%)	100%	
9 Chains / shafts / gear wheels (%)	100%	
10 Drive chains	100%	
11 Hoses central lubrication	100%	
Undercarriage		
12 Track plates / tyres (%)	100%	
13 Track gear wheels (%)	100%	
14 Track rollers / Track tensioners	100%	
Augers		
15 Flights, bearing protectors and shafts (%)	100%	
16 Auger drive case	100%	
17 Centre auger drive	100%	
18 Outer auger drive	100%	
19 Outer auger bearings	100%	

	Condition (1 - 5)	Remarks (mm / %)
Electrics / Lev. System / Drive/ Engine		
20 Cable looms, switches etc.		100%
21 Battery	5	
22 Grade control	5	
23 Slope control	5	
24 RSS, Big Ski or similar system	//	
25 Diesel engine	5	
26 Pump distributor gear	//	
27 Hydraulic pumps	5	
28 Hydraulic motors	5	
29 Valves, valve blocks	5	
30 Steering	5	
31 Brakes, parking brake	5	
32 Hoses, tubing (paver)	5	
Screed		
33 Base plates (mm)		10 mm
34 Tamper bars (%)	90%	
35 Shafts, bearings, lube system	5	
36 Vibrator shafts, bearings	5	
37 Hydraulic motors	5	
38 Vario cylinders, cylinder guides	5	
39 Hoses, tubing	5	
40 Gas / Diesel heating	//	
41 Electric heating	5	

5. General comments on the machine:

Ex Demonstration unit in perfect condition ready for working

Special design:

(This assessment is valid for 1 month or 100 hours. Thereafter a new assessment is required).

Trade-in Price

EUR _____

Date, Name/Signature

MACHINE PARTS SERVICE

